


1	1	20
---	---	----

20	1	1	1	9
----	---	---	---	---



PCB HOLE

1. OPEN, SHOT 전수 검사
2. PIN 3번 빠지거나 밀림 주의
3. 표시 A 부분 오므림 작업 할 것.

[illegible]15
017