



REVISION		
REV	DESCRIPTION	DATE
IR	Initial Registration	2010. 03. 08.
A	부적합 개선 [설변 NO. 201003-0013] 설계 오류로 인한 부품 변경	2010. 03. 11.



주 기
1. 그림 A 참조

3	INSULATOR	1	TEFLON		DAI00114-N/2 DAI00114-N/1
2	CONTACT	1	BeCu	Gold Plated	DAC00203-5/2 DAC00203-5/1
1	BODY	1	MBsBD	Nickel Plated	DAD00208-5/2 DAD00208-5/1
NO.	DESCRIPTION	Q'TY	MATERIAL	PLATING	CODE

TOLERANCE	Decimal	DATE 2010. 03. 11.			 RF & MICROWAVE TECHNOLOGY Tel : 82-32-347-8015 Fax : 82-32-347-8017			
	Angle	APPROVED BY	Y.H.CHOI					
	±1°	CHECKED BY	I.C.KIM					
MATERIAL		DRAWN BY		D.W.KANG		TITLE ADAPTOR		
-								
FINISH	-	SCALE	UNIT		A4	DWG NO.	AD00430-7/2	
		2/1	mm			REVISION	A	SHEET