

A schematic diagram of a piezoelectric actuator assembly. The assembly consists of a long central piezoelectric actuator (labeled 1) connected to two end fittings. The left fitting includes a valve body (labeled 2) and a connector (labeled 4). The right fitting includes a connector (labeled 3). A dimension line at the bottom indicates the length of the piezoelectric actuator as L .

1. RoHS & Pb-FREE
2. CONNECTOR FINISHES
 - 2-1. MCX PL-----▶ BODY : Gold Plating
CONTACT : Gold Plating
 - 2-2. SMA JS-----▶ BODY : Gold Plating
CONTACT : Gold Plating

