



REVISION		
REV	DESCRIPTION	DATE
IR	최초 개정	2001.06.25.
A	[설번처리 No.200812-0016] 부품 치수 부적합으로 인한 조립 불가 INSULATOR 전장 길이 변경	2008.12.29.



7	WASHER	1	MBsBD	Nickel Plate	DWA00022-5/1 (Q6008)
6	NUT	1	MBsBD	Nickel Plate	DNT00020-5/1 (N6002)
5	BACK NUT	1	MBsBD	Nickel Plate	DBN00069-5/1 (P6426)
4	INSULATOR	1	TEFLON		DIN00431-N/1 (H6010)
3	INSULATOR	1	TEFLON		DIN01470-N/1 DIN00587-N/1 (H6509)
2	CONTACT	1	BeCu	Gold Plate	DCT00498-5/1 (E6479)
1	BODY	1	MBsBD	Nickel Plate	DBD00626-5/1 (D6491)
NO.	DESCRIPTION	Q'TY	MATERIAL	PLATING	CODE

A

TOLERANCE	Decimal	DATE 2008. 12. 29.		 RF & MICROWAVE TECHNOLOGY Tel : 82-32-347-8015 Fax : 82-32-347-8017
	Angle	APPROVED BY	S.J.YOUN	
MATERIAL	_____	CHECKED BY	E.H.KIM	KJ COMTECH CO.,LTD. TITLE BNC75-BJ-3C-179
		DRAWN BY	I.C.KIM	
FINISH	_____	SCALE	UNIT	A4 DWG NO. CN00335-7/2 REVISION A SHEET 1 of 1
		2.5/1	mm	