


REVISION				
REV	DESCRIPTION	DRAWN	APPR	DATE
IR	Initial Registration	S.Y.EUN	I.C.KIM	2020.08.13.
1	억지끼움 및 방수 오링 조립 개선으로 인한 부품 변경	S.Y.EUN	I.C.KIM	2020.10.28.
2	ASS'Y 작업후 핀 밀림 현상 개선 핀 뉴시턱 추가	S.H.KIM		2023.04.12.


5/8-24 UNEF-2A



■조립 및 취급시 주의사항

1. 가공 이후 적재, 포장, 이동시 스크래치 주의 요망
2. 부품 조립시 스크래치 주의 요망
3. 포장시 스크래치 발생이 되지 않도록 트레이
한구당 하나씩 포장할 것 (적재 및 이동시 스크래치 주의)
4. 스크래치 발생이 되면 염수분무 Fail 될 수 있음 (주의)

1	6	GASKET	1	SILICONE	RED	DGK00028-N/1 DGK00194-N/1
	5	INSULATOR	1	TEFLON		DIN03162-N/1
2	4	FERRULE	1	MBsBD C3604BD-F	Nickel Plate	DFE00059-5/1
	3	CONTACT	1	BeCu C17300	Gold Plate	DCT04143-5/2 DCT04143-5/1
1	2	BODY	1	MBsBD C3604BD-F	binary alloy(SU) (이원합금)	DBD04641-5/2 DBD04641-5/1
	1	BODY	1	MBsBD C3604BD-F	binary alloy(SU) (이원합금)	DBD04640-5/1
	NO.	DESCRIPTION	Q'TY	MATERIAL	PLATING	CODE



TOLERANCE	Decimal ±0.1	DATE 2023. 04. 12.		 RF & MICROWAVE TECHNOLOGY Tel : 82-32-347-8015 Fax : 82-32-347-8017
	Angle ±1°	APPROVED BY		
MATERIAL _____	CHECKED BY			TITLE N50 CABLE JS 3D-FV
	DRAWN BY	S.H.KIM		
FINISH _____	SCALE 2.5/1	UNIT mm		A4
	DWG NO. CN03943-7/1			
REVISION		2	SHEET 1 of 1	