



* Test Data (Graph)

1. Up Link


Insertion Loss # Return Loss




#Pass Band Ripple



#Attenuation[1937.5/1962.5MHz]




#Group Delay[FA 별 편차




	Date	Version No.	1.0
	Customer	KJ Code	FT00319-6/1


#Attenuation[9KHz~800MHz]




#Attenuation[800~1870MHz]



#Attenuation[2300~2700MHz]




#2nd Harmonic




	Date	Version No.	1.0
	Customer	KJ Code	FT00319-6/1


#Attenuation[2700MHz~12.75GHz]




#Isolation



#Coupling Value[ANT Port Out]




#Coupling Port Directivity




2. Down Link


#Insertion Loss #Return Loss




#Pass Band Ripple



Group Delay




Attenuation[9KHz~800MHz]




	Date	Version No.	1.0
	Customer	KJ Code	FT00319-6/1


Attenuation[800~1870MHz]




Attenuation[2300~2700MHz]



2nd Harmonic




Isolation



	Date	Version No.	1.0
	Customer	KJ Code	FT00319-6/1

Coupling Value[ANT Port Out]



Coupling Port Directivity

