



REVISION				
REV	DESCRIPTION	DRAWN	APPR	DATE
IR	Initial Registration			2003. 12. 16.
1	[설변No. 연구200903-0026] 신뢰성 향상 (BODY 내부 뒤틀림을 추가)			2009. 05. 06.
2	[설변처리No. 201306-0007] 신뢰성 향상 (BODY,PIN 불량 추가,토크 명기)	E.H.KIM	I.C.KIM	2013. 06. 17.



2 주 기

Torque Wrench 200kg 적용 할 것.

3	INSULATOR	1	TEFLON	White	DIN00670-N/1 (H8201)
2	CONTACT	1	BeCu	Gold Plate	DCT00713-5/1 (E8263)
1	BODY	1	MBsBD	Nickel Plate	DBD00951-5/2 DBD00951-5/1 (D8279)
NO.	DESCRIPTION	Q'TY	MATERIAL	PLATING	CODE

TOLERANCE	Decimal	DATE 2013. 06. 17.			 RF & MICROWAVE TECHNOLOGY Tel : 82-32-347-8015 Fax : 82-32-347-8017			
	Angle	APPROVED BY	I.C.KIM					
MATERIAL	-	CHECKED BY	TITLE N50 SOLDER END JB (F/F)					
		DRAWN BY				E.H.KIM		
FINISH	-	SCALE	UNIT		A4	DWG NO.	CN00800-7/1	
		3/1	mm			REVISION	2	SHEET

A4