


REVISION				
REV	DESCRIPTION	DRAWN	APPR	DATE
IR	Initial Registration	S.Y.EUN	I.C.KIM	2017.11.09.
1	[설변No.202201-0009] PIPE 압착 후 BURR 발생 개선으로 인한 PIPE 변경	S.Y.EUN	S.H.KIM	2022.01.17.
2	FERRULE 구성 변경 - 압착시 BURR발생	S.H.KIM		2024.01.05.



5	INSULATOR	1	TEFLON		DIN02953-N/1
4	FERRULE	1	MBsBD C3604BD-F	Nickel Plate	DFE00182-5/1 DFE00018-5/3
3	CONTACT	1	MBsBD C3604BD-F	Gold Plate	DCT00100-5/1
2	CONTACT	1	BeCu C17300	Gold Plate	DCT03891-5/1
1	BODY	1	MBsBD C3604BD-F	Gold Plate	DBD04361-5/1
NO.	DESCRIPTION	Q'TY	MATERIAL	PLATING	CODE

TOLERANCE	Decimal ±0.2	DATE 2023. 01. 05.			 RF & MICROWAVE TECHNOLOGY Tel : 82-32-347-8015 Fax : 82-32-347-8017
	Angle ±1°	APPROVED BY			
MATERIAL _____		CHECKED BY	TITLE SMA50 CABLE JS-2H RG178		
		DRAWN BY S.H.KIM			
FINISH _____		SCALE 4/1	UNIT mm		A4
				DWG NO. CN03740-7/1	
				REVISION 2	SHEET 1 of 1