



1 2 3 4 5 6

REVISION

REV	DESCRIPTION	DATE
IR	Initial Registration	2010. 06. 09.
A	[설번No.201006-0010]작업성 향상 은뎡작업 부적합으로 인한 설변	2010. 06. 09.



7	COVER	1	MBsBD	Nickel Plate	DCO00046-5/1
6	INSULATOR	1	TEFLON		DIN01802-N/1
5	INSULATOR	1	TEFLON		DIN01801-N/1
4	GASKET	1	NBR(BLACK)		DGK00031-N/1
3	CONTACT	1	MBsBD	Gold Plate	DCT02292-5/1
2	CONTACT	1	BeCu	Gold Plate	DCT02291-5/1
1-2	BODY(B)	1	MBsBD	Nickel Plate	DBD02786-3/1
1-1	BODY(A)	1	MBsBD	Nickel Plate	DBB00268-5/1 DBD02785-3/1
NO.	DESCRIPTION	Q'TY	MATERIAL	PLATING	CODE

TOLERANCE	Decimal	DATE 2010. 06. 09.		 RF & MICROWAVE TECHNOLOGY Tel : 82-32-347-8015 Fax : 82-32-347-8017
	Angle	APPROVED BY	Y.H.CHOI	
MATERIAL	-	CHECKED BY	I.C.KIM	TITLE N-LJ-H4-R
		DRAWN BY	D.W.KANG	
FINISH	-	SCALE	UNIT	DWG NO. CN02581-7/2 REVISION A SHEET 1 of 1
		2/1	mm	

1 2 3 4 5 6