



REVISION				
REV	DESCRIPTION	DRAWN	APPR	DATE
IR	Initial Registration	I.C.KIM		2021.09.15.
1	BOM구성 오류로 인한 PIN코드 변경	S.Y.EUN	I.C.KIM	2021.10.18.

5/8-24 UNEF-2A



4	GASKET	1	SILICONE RUB		DGK00269-N/2
3	INSULATOR	1	TEFLON		DIN02103-N/1
2	CONTACT	1	BeCu C17300	Silver Plate (3μm 이상)	DCT04264-5/1 DCT04257-5/1
1	BODY	1	MBsBD C3604BD-F	SUCO Plate (3μm 이상)	DBD03968-5/1
NO.	DESCRIPTION	Q'TY	MATERIAL	PLATING	CODE

TOLERANCE	Decimal	DATE 2021. 10. 18.			 RF & MICROWAVE TECHNOLOGY Tel : 82-32-347-8015 Fax : 82-32-347-8017			
	Angle	APPROVED BY I.C.KIM						
		$\pm 1^{\circ}$	CHECKED BY			TITLE N50 SOLDER END JS-4H		
MATERIAL		DRAWN BY S.Y.EUN						
FINISH		SCALE 3/1	UNIT mm		A4	DWG NO. CN04022-7/1		
						REVISION 1	SHEET 1 of 1	