



1. Measurement Data


SUM, P1 (VSWR, LOSS, PHASE)




SUM, P2 (VSWR, LOSS, PHASE)




SUM, P3 (VSWR, LOSS, PHASE)




SUM, P4 (VSWR, LOSS, PHASE)




SUM, P5 (VSWR, LOSS, PHASE)




SUM, P6 (VSWR, LOSS, PHASE)




P1, P2 isolation




P1, P3 isolation




P1, P4 isolation




P1, P5 isolation




P1, P6 isolation




P2, P3 isolation




P2, P4 isolation




P2, P5 isolation




P2, P6 isolation




P3, P4 isolation




P3, P5 isolation




P3, P6 isolation



P4, P5 isolation



P4, P6 isolation



P5, P6 isolation

