


REVISION				
REV	DESCRIPTION	DRAWN	APPR	DATE
IR	Initial Registration	I.C.KIM	I.C.KIM	2014.12.05.
1	[설번No.202201-0009] PIPE 압착 후 BURR 발생 개선으로 인한 PIPE 변경	S.Y.EUN	S.H.KIM	2022.01.10.



8	WASHER	1	SK-5	Nickel Plate	DWA00003-5/1
7	NUT	1	MBsBD	Nickel Plate	DNT00025-5/5
6	INSULATOR	1	TEFLON		DIN00126-N/2
5	GASKET	1	NBR		DGK00017-N/1
4	FERRULE	1	MBsBD	Nickel Plate	DFE00018-5/3 DFE00152-5/1
3	CONTACT	1	MBsBD	Gold Plate	DCT00100-5/1
2	CONTACT	1	BeCu	Gold Plate	DCT03312-5/1
1	BODY	1	MBsBD	Nickel Plate	DBD03796-5/1
NO.	DESCRIPTION	Q'TY	MATERIAL	PLATING	CODE

TOLERANCE	Decimal	DATE 2022. 01. 10.		 RF & MICROWAVE TECHNOLOGY Tel : 82-32-347-8015 Fax : 82-32-347-8017
	Angle	APPROVED BY	S.H.KIM	
MATERIAL		CHECKED BY		KJ COMTECH CO.,LTD. TITLE BMA50 CABLE PB RG178
		DRAWN BY	S.Y.EUN	
FINISH		SCALE	4/1	A4 DWG NO. CN03338-7/1 REVISION 1 SHEET 1 of 1
		UNIT	mm	