



* Test Data(Graph)

1. Up Link


Insertion Loss # Return Loss




Pass Band Ripple



Attenuation[1937.5MHz/1962.5MHz]




Group Delay




	Date	Version No.	1.0
	Customer	KJ Code	FT00311-6/1


Attenuation[9KHz~800MHz]




Attenuation[800MHz~1870MHz]



Attenuation[2.3GHz~2.7GHz]




Harmonic[2nd]




	Date	Version No.	1.0
	Customer	KJ Code	FT00311-6/1


Isolation




Output Coupling Value



Directivity




Attenuation[2.7~12.75GHz]




2. Down Link

Insertion Loss # Return Loss




Pass Band Ripple




	Date	Version No.	1.0
	Customer	KJ Code	FT00311-6/1


Attenuation[9KHz~800MHz]




Attenuation[800~1870MHz]



Attenuation[2.3~2.7GHz]




Harmonic[2nd]




	Date	Version No.	1.0
	Customer	KJ Code	FT00311-6/1

Isolation



Input Coupling Value



Directivity

